




Legacy Laboratory Services

Legacy LabAlert

An Important Update from Legacy Laboratory Services

October 2020

Due to a recent FDA requirement, Medline (the supplier for the sterile container cups) has updated the manufacturer label which is located on the outside of the cup. This update includes a barcode which runs along the side of the label. This is lawson # 370167

Container	Label Placement Examples
<p>Preferred Patient Label placement:</p> <ul style="list-style-type: none">✓ Patient label applied over the manufacturer's barcode label✓ Applied vertically to container for ease of scanning	
<p>NOT Preferred Patient Label placement:</p> <ul style="list-style-type: none">✗ Too close to manufacturer's barcode which can interfere with scanning the patient's barcode on the label	
<p>Manufacturer's barcode label</p> <ul style="list-style-type: none">✗ Used by the manufacturer to track lots✗ Do not scan for patient testing	



Legacy Laboratory Services

For additional information, please contact your account representative, client services or consult our website:

Legacy Laboratory Client Services: 503-413-1234, 877-270-5566, www.legacyhealth.org/labservices